

From: [<Wallingford, Jonni B. >wallingfordjb@cdmsmith.com>](mailto:wallingfordjb@cdmsmith.com)
To: [<Sheldrake, Sean >sheldrake.sean@epa.gov>](mailto:sheldrake.sean@epa.gov)
[<Zhen, Davis >Zhen.Davis@epa.gov>](mailto:Zhen.Davis@epa.gov)
CC: younghs@cdmsmith.com
[<Scott Coffey >coffeyse@cdmsmith.com>](mailto:coffeyse@cdmsmith.com)
[<Jusayan, Mark A. >jusayanma@cdmsmith.com>](mailto:jusayanma@cdmsmith.com)
Date: 8/6/2018 10:10:49 AM
Subject: Subsurface Sediment Coring Observed Sheen
Attachments: [IMG_20180806_095601630.jpg](#)
[IMG_20180806_095914343_HDR.jpg](#)
[IMG_20180806_095938832_HDR.jpg](#)
[IMG_20180806_095951219_HDR.jpg](#)

Good morning,

Included are photos of the Cayuse crew prepping to core Gas Co. site: SC-S105 /RM 6.1. See photo 1: observed sheen in river prior to coring

The SMA has a water depth of 2.8 ft. NRC is onsite applying sweep booms around coring region in a row boat, considering low water levels.

Jonni

Photo 1: sheen

Photo 2: NRC applying boom

Photo 3: sweep boom

Photo 4: NRC applying sweep boom

Get Outlook for Android<<https://aka.ms/ghei36>>